

Aluminium Alloys (Filler Rods & Wires)

SM 1100



 **SENOR[®]**
One Stop Solution for Welding & Brazing Consumables

SM 1100

Aluminum Low Alloyed

Al Filler Metal

Classifications:

AWS / SFA5.10	: ER 1100
UNS No.	: A91100
DIN 1732	: SG-Al 99.8
ISO 18273 Numerical	: Al1100
ISO 18273 Chemical	: Al-99.0.Cu

Description:

Senor SM1100 is highly resistant to chemical attack and weathering and has good crack resistance. It has highest electrical and thermal conductivity. It has excellent fluidity. Deposit is soft and ductile.

Technical Data:

UTS	: 6-9 Kgf/mm ²
YS	: 4-6 Kgf/mm ²
Elongation (L=D)	: 42%
Melting Point	: 643-658°C
Resistance to Corrosion	: A (Gen) A (SCC)
Anodize Color	: Light Golden
Electrical Conductivity	: 59% IACS (-H12)
Density	: 2.71 gms/cc
Shielding gas	: 100% Argon , Argon/Helium Mixtures , Flow Rate: 30 - 50 CFH (14.2 - 23.6 L/Min)



Chemical Composition (%):

Si +Fe	Al	Zn	Cu	Mn	Be	Other Each	Other Total
0.95	99	0.10	0.05-0.20	0.05	0.0003	0.05	0.15

Flame Adjustment:

1-1 ½ X Carburizing flame to be used for brazing use flux.

Typical Applications:

- Suitable for electrical and chemical application utilizing little or no alloying elements, 1000 series
- Heat Exchanger
- Metalizing
- Tank, Brackets, Bus Bodies.

Availability :

Standard Size	: 1.6, 2.0, 2.5, 3.2 & 4.0 mm dia in 500 / 1000 mm length
Packing	: 500 mm in 2 kg. & 1000 mm in 5 kg. for TIG welding
Spools	: 0.8, 1.2 & 1.6 mm dia in 6.5 kg. spool for MIG welding

Note On Usage:

- 1) Follow the recommended welding parameters to achieve good sound welds
- 2) Do not use excessive currents. Hold short arc. Use good fit-up on joints.

Above are basic guidelines and will vary depending on joint design, number of passes and other factors.

⚠WARNING ⓘ

Protect yourself and others. Read and understand this warning. Do not remove this warning.

Fumes and Gases can be hazardous to your health

- Before use, read and understand the Material Safety Data Sheet (MSDS), the manufacturer's instructions, and your employer's safety practices.
- If MSDS is not enclosed. Obtain from your employer.
- Keep your head out of the fumes. See Section 5 of the MSDS for specific fume concentration limits.
- Use enough Ventilation, exhaust at the arc, or both, to keep fumes and gases from your breathing zone and the general area. If needed, use a proper respirator.
- No hazards exist before this product is used in arc welding.

Electric Shock can kill

- Always wear dry insulating gloves
- Insulate yourself from work and ground.
- Do not touch live electrical parts.

ARC Rays can injure eyes and burn skin

- Wear welding helmet with correct filter.
- Wear correct eye, ear, and body protection.

Welding can cause fire or explosion

- Do not weld near flammable material.
- Watch for fire, keep, extinguisher nearby.

Read American National Standards Z49.1, "Safety In Welding, Cutting and Allied Process." from American Welding Society.